

FIG. 1A
Prior Art

FURNACE CURE / POROGEN BURNOUT




FIG. 1B



FIG. 2A

HOT PLATE BAKE / PARTIAL BURNOUT
OR SURFACE POROGENS




FIG. 2B

APPLICATION OF ETCH STOP LAYER
AND TOP POROUS SILK LAYER




FIG. 2C

FURNACE CURE / POROGEN BURNOUT




FIG. 2D




FIG. 3




FIG. 4